



## Corrigendum

## Corrigendum to “Measurements of strain and humidity within massive concrete cylinders related to the formation of ASR surface cracks” [Cement and Concrete Research. 41 (2011) 808–816]


Hiroyuki Kagimoto<sup>a,\*</sup>, Mitsunori Kawamura<sup>b</sup>

<sup>a</sup> Civil Engineering Laboratory, Electric Power Development Co., Ltd., 9-88, Chigasaki, Kanagawa, Japan

<sup>b</sup> Kanazawa University, Kakuma, Kanazawa, Japan

The authors regret that in the above mentioned article, Fig. 12 contained errors. The corrected Fig. 12 can be found below.

The authors would like to apologise for any inconvenience this may have caused to the readers of the journal.



DOI of original article: [10.1016/j.cemconres.2011.03.010](https://doi.org/10.1016/j.cemconres.2011.03.010).

\* Corresponding author.